

## Replacement Chamber Kits

**2020**

### New Items for 2020



1185  
Burnham Target  
from 1064/  
1066/1074/1129

1186  
Burnham LE  
Door Insulation  
from 1167

1187  
Metromatic Small  
Chamber

1188  
Metromatic Large  
Chamber

1189  
Reznor Water Oil  
Tombstone

← Click the item number to be linked to the specification sheet

MANUFACTURER MODEL	LYNN ITEM #	MANUFACTURER MODEL	LYNN ITEM #	MANUFACTURER MODEL	LYNN ITEM #
<b>AIRCO</b> -See Olsen/Airco		<b>BURNHAM (continued)</b>		<b>CARRIER</b>	
<b>AMERICAN STANDARD</b>		<b>V3 SERIES</b>		<b>PERFORMANCE 86</b>	
<b>ARCOLIDER WET BASE</b>		OEM #8202307 & 8202301 -- <a href="#">1065</a>		<b>BW4 &amp; BW5 BOILERS</b>	
Quickie, See Table Page 4		V33, V34, V35 & V36		NO Swing-Out Door- ----- <a href="#">1105</a>	
<b>A-3 SERIES</b> ----- <a href="#">1065</a>		<b>V7 SERIES</b>		With Swing-Out Door ----- <a href="#">1132</a>	
A33, A34, A35, A36 & A37		V72, V73, V713, V74, V714,		<b>COLUMBIA</b>	
<b>ARCOLINER WET BASE</b>		V75, V76, V77, V78		<b>CSF SERIES</b>	
Quickie, See Table Page 4		NO Swing-Out Door- ----- <a href="#">1066</a>		CSF-365, CSF-3100, ----- <a href="#">1095</a>	
<b>VP(T)</b> - All models ----- <a href="#">1064</a>		OEM #8202701 & #8202702		CSF-4125, CSF-4150,	
<b>V-3</b> - All models ----- <a href="#">1065</a>		With Swing-Out Door ----- <a href="#">1074</a>		CSF-5175, CSF-5200	
		OEM #8202701 & #8202701		CSF-6225, CSF-7280	
		<b>V8 / V8H SERIES</b>		<b>CSFH-3 &amp; CSFE</b>	
		OEM# 8202701 & #82028004		CSF(H or E)-365, 3100, --- <a href="#">1096</a>	
<b>BARD OIL FURNACES</b>		V82, V83, V84, V85, ----- <a href="#">1129</a>		3125, 4100, 4125, 4150,	
OEM #7090-005 ----- <a href="#">1131</a>		V86, V8H2, V8H3, V8H4,		5125, 5175, 5200, 6150,	
Fits Models: D36C, D48C,		V8H5, V8H6		7275	
D60C, F81, F86CF, F86H,		V87, V88, V89 ----- <a href="#">1130</a>		<b>LV &amp; LVD SERIES</b>	
F97, F100CF, FC085,		V8H7, V8H8, V8H9		OEM #337801, #337816, --- <a href="#">1172</a>	
FH085, FH110, FLF085,		<b>JUBILEE WET BASE</b> ----- <a href="#">1086</a>		#337803, 337804	
FLF110, FLR085, FLR110		230, 235, 240, 245, 250,		<b>EMERALD</b>	
		255, 260		OEM #337345 ----- <a href="#">1175</a>	
<b>BRYANT -PREFERRED SERIES</b>		<b>MPO</b>		EM-85(E), 100(E),	
<b>BW4 &amp; BW5 BOILERS</b>		MPO-IQ84 & IQ115 ----- <a href="#">1177</a>		110(E) & 125(E)	
NO Swing-Out Door- ----- <a href="#">1105</a>		MPO-IQ147 & IQ189		<b>CROWN</b>	
With Swing-Out Door ----- <a href="#">1132</a>		MPO-IQ231 ----- <a href="#">1178</a>		<b>BAHAMA</b>	
<b>BURNHAM</b>		<b>MEGASTEAM</b>		OEM #14614015 & 14619003 --- <a href="#">1105</a>	
<b>C3 &amp; C4 SERIES</b> ----- <a href="#">1074</a>		MST228, MST396, MST513 --- <a href="#">1177</a>		BD-74, BD-91, BD-111,	
<b>LE &amp; LEDV</b> - All Models		MST629 ----- <a href="#">1178</a>		BD-120, BD-147, BD-151,	
LE1, LE2, LE1-L, LE1-H, DV <a href="#">1167</a>		<b>RS SERIES</b>		BD-178, BD-211, BD-238	
OEM 8203301, 8203302,		RS-109, RS-110, RS-111 --- <a href="#">1107</a>		<b>BAHAMA SWING-OUT</b>	
8203303		RS-112, RS-113, RS-114		OEM #14619003 & 14614014 --- <a href="#">1132</a>	
<b>3W &amp; 4W SERIES</b> ----- <a href="#">1074</a>		<b>RSM SERIES</b>		BDS-80, BDS-92, BDS-111,	
<b>V1 SERIES</b>		RSM-96, RSM-126 ----- <a href="#">1107</a>		BDS-119, BDS-147, BDS-150	
OEM 8202211, ----- <a href="#">1064</a>		<b>RSA SERIES</b>		BDS-178, BDS-209, BDS-236	
8202701 & 8202210		RSA-85, 110, 125 & 135 -- <a href="#">1173</a>			
V13, V14, V15, V16, V17,					
V18, V172, V196					

MANUFACTURER & MODEL #	LYNN ITEM #	MANUFACTURER & MODEL #	LYNN ITEM #	MANUFACTURER & MODEL #	LYNN ITEM #
<b>CROWN (continued)</b>		<b>HYDROTHERM (continued)</b>		<b>NEW YORKER (continued)</b>	
<b>FREEMPORT II</b>		<b>PB SERIES</b>		<b>MICROTEK</b>	
FWZ060, 080, 100, 130---	<a href="#">1177</a>	PB-105, PB-120, PB-150, PB-180, PB-200, PB-235, PB-245, PB-295		3 & 3DV-All Models-----	<a href="#">1167</a>
FSZ080, 100, 130		NO Swing-Out Door-----	<a href="#">1104</a>	OEM 8203301, 8203302, 8203303	
FWZ160 & FSZ160 -----	<a href="#">1178</a>	With Swing-Out Door -----	<a href="#">1153</a>	<b>FR SERIES</b>	
<b>TOBAGO &amp; KINGSTON</b>		<b>KERR</b>		<b>COMBUSTION CHAMBER KITS</b>	
TWZ & KSZ - ALL SIZES -----	<a href="#">1155</a>	<b>F70, F75 &amp; F100</b>		FR-HGS 98 & 122, -----	<a href="#">1161</a>
		See Valliant Listing		FR-HGSII 98 & 122 OEM #62072001	
<b>DUNKIRK</b>		<b>LAARS</b>		FR-147, 173, 205, 232 ----	<a href="#">1162</a>
<b>13 &amp; 15 SERIES</b>		<b>NEWPORT</b>		OEM #62072002	
Quickie, See Table Page 4		OEM #51-088 -----	<a href="#">1174</a>	FR-265 & 305 -----	<a href="#">1163</a>
<b>EMPIRE WATER</b>		NP-85, 100 & 110		OEM #62072003	
OEM #14614015 & 14619003 ---	<a href="#">1105</a>	<b>LENNOX</b>		<b>FLUE BOX KITS</b>	
3E.60 (C), 3E.75 (C), 3E1.00 (C), 4E.90 (C), 4E1.25 (C), 4E1.50 (C) 5E1.20 (C), 5E1.75 (C), 5E2.00 (C)		<b>CONSERVATOR SERIES</b>		FR-HGS 98 & 122-----	<a href="#">1164</a>
<b>EMPIRE II WATER</b>		COWB-3, 4&5 -----	<a href="#">1105</a>	OEM #62072006	
OEM #14619003 & 14614014 ---	<a href="#">1132</a>	COWB2-3, 4 & 5 -----	<a href="#">1132</a>	FR-HGSII-----	<a href="#">1165</a>
3EW.65, 3EW.75, 3EW1.00, 4EW.90, 4EW1.25, 4EW1.50, 5EW1.20, 5EW1.75, 5EW2.00		<b>MILLER/NORDYNE</b>		OEM #62072007	
<b>EMPIRE STEAM II</b>		<b>MOBILE HOME</b>		FR-147 & 173 -----	<a href="#">1166</a>
ESB or ESC0365, 3100 -----	<a href="#">1096</a>	CMF, MOC & MGC -----	<a href="#">1029</a>	OEM #62072008	
4100, 4125, 4150, 5175, 5200, 6225 & 7275		OEM #901818 CMF2 -----	<a href="#">1141</a>	<b>NY SERIES</b>	
<b>EV SERIES</b>		<b>M1/M5 SERIES</b>		NY-124-1, NY-151-1 -----	<a href="#">1106</a>
DPFO-3 -----	<a href="#">1075</a>	OEM #903423 -----	<a href="#">1141</a>	NY-168-1, NY-194-1, NY-224-1	
DPFO-3T, 4, 4T, 5, 5T ----	<a href="#">1073</a>	Fits all M1S, M1B & M5S		<b>AP SERIES</b>	
DPFO-6T,7, 8T & 9		<b>MEMCO</b>		AP-490, AP-510, -----	<a href="#">1103</a>
<b>ELECTRIC FURNACE-MAN</b>		<b>SST SERIES</b>		AP-590 AP-670, AP-690, AP-790, APD-96	
<b>OBT-5 SERIES</b>		NO Swing-Out Door-----	<a href="#">1105</a>	AP-780, AP-840, -----	<a href="#">1106</a>
OBT75C5, OBT100C5, ---	<a href="#">1067</a>	With Swing-Out Door -----	<a href="#">1132</a>	AP-890, AP-1160	
OBT125C5, OBT150C5, OBT175C5, OBT200C5 OBT250C5, OBT275C5, OBT300C5		<b>CST-PLUS</b>		<b>AP-U SERIES</b>	
<b>METROMATIC</b>		CSTO-3 -----	<a href="#">1075</a>	AP-490U, AP-590U, -----	<a href="#">1173</a>
LB/HBSU 84, 100, 120 -----	<a href="#">1187</a>	CSTO-3T,4,4T,5&5T -----	<a href="#">1073</a>	AP-690U, AP-790U	
LB/HBSU 140, 200, 275 -----	<a href="#">1188</a>	CSTO-6T, 7, 8T, 9		<b>S or KD SERIES</b>	
<b>HYDROTHERM</b>		<b>NEW YORKER BOILER</b>		97-AP, 107-AP,-----	<a href="#">1103</a>
<b>OR SERIES</b>		OEM #C11750 -----	<a href="#">1103</a>	118-AP131-AP, 154-AP-----	<a href="#">1106</a>
OR-175, 210 & 280 -----	<a href="#">1077</a>	OEM #8203006 -----	<a href="#">1173</a>	114-AP, 122-AP, 132-AP 142-AP, 165-AP, 176-AP, 193-AP, 203-AP, 222-AP, 230-AP, 500, 580, 660, 720, 840, 990	
OR-330 & 385 -----	<a href="#">1078</a>	OEM #PC12000 -----	<a href="#">1106</a>	<b>PH SERIES</b>	
<b>MULTITEMP</b>		<b>CI-HGS SERIES</b>		PH-132, PH-142, PH-154-----	<a href="#">1106</a>
MO/G-420, 560, 660 -----	<a href="#">1077</a>	CI-HGS-74B & 101B -----	<a href="#">1177</a>	PH-165, PH-176, PH-203 ,PH-222, PH-230, CPH-165, CPH-176	
840, 990, 1320		CI-HGS-129B & 167B		<b>OS SERIES</b>	
MO/G-770, 1155, 1320---	<a href="#">1078</a>	<b>CLASSIC SERIES</b>		OS-123-1 & 140-1 -----	<a href="#">1103</a>
1540, 1925, 2310, 2695 3080, 3465, 3850, 4235 4620, 5005, 5390, 5775 6160, 6545, 6930A		CLW-3, 4, 5 & 6 -----	<a href="#">1134</a>	OS-101-1, 113, 120-1 ----	<a href="#">1106</a>
		CL-3S, 4S, 5S, 6S& 7S OEM #121900 & #8202701		122, 132, 142, 143-1, 161-1, 165, 170-1, 191-1, 222	
		CL3-091, 105 & 140 ----	<a href="#">1155</a>	<b>UCG SERIES</b>	
		CL4-126, 175 & 210 CL5-168, 245 & 280 OEM #270021 & #270025		UGC-100- -----	<a href="#">1103</a>
		NO Swing-Out Door-----	<a href="#">1134</a>	UGC-100, 125, 125-1 -----	<a href="#">1106</a>
		With Swing-Out Door &-----	<a href="#">1155</a>	140,150-1, 154-1, 164, 170, 189-1	
		Observation Hole on Right Side		<b>WH SERIES</b>	
		With Swing-Out Door &-----	<a href="#">1074</a>	WH-132, WH-142, -----	<a href="#">1106</a>
		Observation Hole on Left Side		WH-154, WH-165, WH-176	

MANUFACTURER & MODEL #	LYNN ITEM #	MANUFACTURER & MODEL #	LYNN ITEM #	MANUFACTURER & MODEL #	LYNN ITEM #
<b>OLSEN BOILERS</b>		<b>PENNCO (continued)</b>		<b>H.B. SMITH (continued)</b>	
<b>OSFH</b> -----	<a href="#">1096</a>	<b>KSC STEAM</b>		<b>SERIES 8HE</b>	
OSFH-365, 3100, 3125, 4100, 4125, 4150, 5125, 5175, 5200, 6150, 6225, & 7275		KSC0365S, KSC3100S -----	<a href="#">1096</a>	8HE-3, 8HE-4, 8HE-5 -----	<a href="#">1071</a>
<b>OLSEN/AIRCO FURNACES</b>		KSC4100S, KSC4125S		<b>SERIES 19</b>	
OEM #9200C, #28562 ----	<a href="#">1158</a>	KSC4150S, KSC5175S		3-6 Section -----	<a href="#">1169</a>
& #8823B1 Firepot		KSC5200S, KSC6225S,		Beckett 3-6 Section-----	<a href="#">1170</a>
BCL-120(S)(ST), 145(S)(ST)		KSC7275S		7-12 Section -----	<a href="#">1171</a>
BFL-120, 120T, 145 & 145T		<b>PUREPRO</b>		<b>SERIES 28- All</b> -----	<a href="#">1168</a>
HTL-100B/C & WTL-100		<b>ADVANTAGE</b>			
<b>ONEIDA ROYAL</b>		AO(T)-3, 4 & 5 -----		<b>TRIANCO</b>	
L-HO-145DA4 -----	<a href="#">1158</a>			<b>DBC</b>	
L-HO-145DA5		<b>REZNOR</b>		OEM #51-088 -----	<a href="#">1174</a>
<b>PEERLESS</b>		<b>RA &amp; RAD Waste Oil Heaters</b>		DBC-85, 100,110 & 115	
<b>EC/ECT</b> - All models		140,150, 235, 250-----		<b>THERMO-DYNAMICS</b>	
OEM #50661, #50768, ---	<a href="#">1093</a>	<b>SEARS</b>		<b>LM &amp; LMD SERIES</b>	
#50765		<b>KENMORE 44</b>		OEM #337801, 337816, -----	
EC-03, EC-04, EC-05, EC-06		94413(C), 94414(C), -----		<a href="#">1172</a>	
ECT-03, ECT-04, ECT-05,		94415(C), 94423(C), 94424(C),		337803, 337804	
ECT-06, CC4028, EC3002		94425(C) 94433(C), 94434(C),		<b>S SERIES</b>	
<b>JO/JOT</b> - All models		94435(C)		OEM #337350 -----	
OEM #50661, #CC-3025--	<a href="#">1067</a>	<b>SLANT/FIN</b>		S or STR-85, 100,	
JO-3, JO-35, JO-4, JO-45,		<b>XL-2000</b>		110, 125, 135 & 150	
JO-5, JO-6, JO-75		XL-20, XL-30, XL-40, XL-50---		<b>THERMOFLO - BOILERS</b>	
JOT-3, JOT-35, JOT-4, JOT-45,		<b>LIBERTY</b> —All Models		<b>OWB, OWT- ALL</b> -----	
JOT-5, JOT-6, JOT-75		P, PT, PPT, PZ, -----		<a href="#">1126</a>	
TWO75, TW100, TW125,		PZT, L-20, L-20BK, L-30H,		<b>OSB, OST- ALL</b> -----	
TW150, TW175, TW200,		L-30HF, L-30, L-40H, L-40,		<a href="#">1126</a>	
TW250, TW275, TW300		L-50H, L-50HF, L-50, L-60,		<b>ULTIMATE ENGINEERING</b>	
<b>SC/SCT</b>		L-70, L-70C, L-70P, L-70PT,		<b>PFO SERIES</b>	
OEM #50768 & #50765 ---	<a href="#">1179</a>	L-70PPT, L-70WKD, L-70WU		PFO-3 -----	
SC-05, SC-06, SC-07,		<b>LIBERTY II</b> —All Models		<a href="#">1075</a>	
SC-08, SC-09, SC-10		LD-20, LD-30H, -----		<a href="#">1073</a>	
SCT-05, SCT-06, SCT-07,		LD-30, LD-40H, LD-40,		6T, 7, 8T, 9	
SCT-08, SCT-09, SCT-10		LD-50H, LD-50, LD-60, LD-70		<b>UTICA RADIATOR</b>	
<b>SERIES CC</b>		<b>INTREPID</b> —All Models		<b>ACE SERIES</b>	
3-6 Section -----	<a href="#">1169</a>	TR-20, TR-30, TR-40, -----		Quickie, See Table Page 4	
Beckett 3-6 Section -----	<a href="#">1170</a>	TR-50, TR-60, TR-70,		<b>O.U. SERIES</b>	
7-12 Section -----	<a href="#">1171</a>	<b>CARAVAN</b> —All Models		Quickie, See Table Page 4	
<b>SERIES TC II</b> - All -----	<a href="#">1168</a>	600-2-5, 750-2-6, -----		<b>STARFIRE II</b>	
<b>WB, WV &amp; WB/WV</b>		850-2-7, 900-3-5, 1100-3-6		OEM #5611508, RD160A-----	
OEM #50795 & 50794 -----	<a href="#">1071</a>	1300-3-7, 1700-4-7, 2100-5-7,		<a href="#">1095</a>	
Fits WB, WV, WV-DV & WBV		2500-6-7, 2900-7-7, 3400-8-7		SF-365, SF-3100, SF-4125	
WB-03, WB-04, WB-05		<b>H.B. SMITH</b>		SF-4150, SF-5175, SF-5200	
<b>PENNCO</b>		<b>BB14 &amp; OB14</b> -All Models		SF-6225, SF-7275	
<b>KEYSTONE WATER</b>		OEM #60462 -----		<b>STARFIRE III &amp; IV</b>	
3K.60(C), 3K.75(C), -----	<a href="#">1105</a>	<a href="#">1159</a>		OEM #2552901, -----	
3K.100(C), 4K.90(C),		<b>FD-12</b>		<a href="#">1096</a>	
4K1.25(C), 4K1.50(C)		All Models -----		2553303, 5611508	
5K1.20(C), 5K1.75(C),		8-W-3, 8-W-4, 8-W-5, 8-W-6		SF(H or E)365, 3085, 3100	
5K2.00(C)		8-S-3, 8-S-4, 8-S-5, 8-S-6		3125, 4100, 4125, 4145,	
<b>NO Swing-Out Door</b> -----		<b>SERIES 8</b>		4150, 5125, 5160, 5175,	
OEM# 69406, 69356		8-W-3, 8-W-4, 8-W-5, 8-W-6		5185, 5200, 6150, 6175,	
With Swing-Out Door -----	<a href="#">1153</a>	NO Swing-Out Door-----		6210, 6225, 7275	
OEM# 69406, 61137,		OEM# 69406, 69356		<b>SW SERIES</b>	
61138, 61136, & 60023		With Swing-Out Door -----		SW3, SW4, SW5 -----	
		OEM# 69406, 61137,		<a href="#">1096</a>	
		61138, 61136, & 60023		<b>CONSTELLATION</b>	
				SFM6225W, 7275W -----	
				<a href="#">1096</a>	
				24150W, 25175W, 25200W,	
				26225W, 27275W, 36225W,	
				37275W, 47275W, 57275W,	
				67275W, 77275W, 87275W	

MANUFACTURER & MODEL #	LYNN ITEM #	MANUFACTURER & MODEL #	LYNN ITEM #	MANUFACTURER & MODEL #	LYNN ITEM #
<b>VAILLANT</b> <b>F70 &amp; F75 SERIES</b> OEM #2015-114 ----- <a href="#">1117</a> F70-40, 45, 50 & 55 F75-40, 45, 50 & 55 <b>F100 SERIES</b> F100-30, 40, 50 & 60 ----- <a href="#">1119</a>		OEM #386-700-355 All WTGO, WGO, SGO 2 Thru 8 Section ----- <a href="#">1072</a> WGO-2, WGO-3, WGO-4, WGO-5, WGO-6, WGO-7, WGO-8 9 SECTION ONLY ----- <a href="#">1148</a> WGO-9 <b>76 SERIES</b> 476, 576R, 576, 676 ----- <a href="#">1120</a> 776, 876, 976 <b>78 &amp; 80 SERIES</b> 4" Burner Opening ----- <a href="#">1121</a> 6" Burner Opening ----- <a href="#">1122</a>		<b>Notes:</b> 1. Combined Kits 1124 replaced by 1067 1114, 1115, 1137, 1138 replaced by 1073 1135 replaced by 1074 1136 replaced by 1075 1099 replaced by 1077 1094 replaced by 1087 1111 replaced by 1095 1116, 1097, 1144, 1147, 1149 replaced by 1096 1123, 1108, 1112, 1139, 1146 replaced by 1105 1125 replaced by 1126 1143, 1150, 1128, 1142 replaced by 1127 1133, 1140, 1151 replaced by 1132 1145 replaced by 1141 1154 replaced by 1153 3. Retired Kits No Longer Available: 1017, 1004, 1061, 1080, 1081, 1082, 1083, 1156, 1180, 1181, 1182, 1183, 1184,	
<b>WEIL MCLAIN</b> <b>65 SERIES</b> 465, 565, 665, 765, 865 -- <a href="#">1101</a> <b>66 SERIES</b> OEM #386-500-085 ----- <a href="#">1060</a> 266, 366, 466, 566, 666, 766 <b>68 / 68V SERIES</b> OEM #386-500-085 ----- <a href="#">1060</a> 268, 368, 468, 568 668, 768, 868, 968 <b>GO SERIES (Gold)</b>		<b>WILLIAMSON - BOILERS</b> <b>OWB, OWT - ALL</b> ----- <a href="#">1126</a> <b>OSB, OST - ALL</b> ----- <a href="#">1126</a>			

### Quickies



Name	Dims	Firing Rate GPH	Item
Quickie 100	11.5" W x 11" L x 10.75" H	0.75— 1.25	<a href="#">1001</a>
Quickie 200	12.25" W x 14.25" L x 12" H	1.35— 1.75	<a href="#">1002</a>
Quickie 300	12.25" W x 18.25" L x 12" H	1.75— 2.25	<a href="#">1003</a>

### Time Saver



Name	Dims	Firing Rate GPH	Item #
Time Saver 9	9" ID x 10.75" OD x 14.5" H	0.65— 0.85	<a href="#">1009</a>
Time Saver 11	11" ID x 12.75" OD x 15.75" H	1.00— 1.25	<a href="#">1011</a>
Time Saver 13	13" ID x 14.75" OD x 15" H	1.35— 1.75	<a href="#">1013</a>



#### Application, Installation and Use Warning:

In applications including; boilers, furnaces, wood stoves, wood inserts, fireplaces, heating devices, and other appliances, parts must be used consistently with original equipment manufacturers specifications, design, function and operation.

Improper installation or use of this product could result in a fire, smoke inhalation or carbon monoxide poisoning. Products should be installed by a licensed and certified technician in compliance with all national, state and local codes. Products should be inspected annually by a licensed and certified technician for wear, brittleness, cracking or crumbling, and replaced as necessary. Lynn Manufacturing, Inc. recommends installers certified by NFI, CSIA or NORA.

Never work on a piece of equipment or touch the fibrous product when it is hot, as the product may show no visible signs of heat from glowing or smoking.

Lynn Manufacturing, Inc offers hundreds of products with many applications. Determining whether the product is a fit for the particular purpose and suitable for an application is the sole responsibility of the purchaser/installer.

In no event shall Lynn Manufacturing, Inc be liable for any damages to property or life arising from or connected with the use of this product.



**Perfect Fit Replacement Kits**  
For 500+ makes & models of  
boilers/furnaces



**Same Day Shipment on  
FedEx & UPS Orders**  
2:30 EST Cut Off Time



**Extensive Inventory**  
Everything in Catalog is Stocked



**Great Customer Support**  
(781) 593-2500  
techsupport@lynnmfg.com

Lynn Manufacturing, Inc  
15 Marion Street  
Lynn, MA 01905

**LYNN**  
MANUFACTURING, INC.

781-593-2500  
orders@lynnmfg.com  
www.lynnmfg.com